

PLAT RECORDING SHEET

PLAT NAME: Tamarron, Section 5

PLAT NO: _____

ACREAGE: 17.235

LEAGUE: J. D. Vermillion Survey

ABSTRACT NUMBER: 339

NUMBER OF BLOCKS: 2

NUMBER OF LOTS: 53

NUMBER OF RESERVES: 4

OWNERS: D. R. Horton – Texas, Ltd.

(DEPUTY CLERK)

BE: CHAS LAMONSON, PEASEBAY

45


—

THENCE, NORTH 76° 34' 27" EAST, 185.00 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 87° 30' EAST, 45.34 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 45° 45' 07" EAST, 104.19 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 84° 34' 14" EAST, 193.14 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 84° 30' 14" EAST, 193.14 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 35° 33' 07" EAST, 40.33 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 84° 17' 00" EAST, 121.02 FEET TO A POINT FOR CORNER;
THENCE, SOUTH 81° 36' 07" EAST, 108.41 FEET TO A POINT FOR CORNER;
THENCE, 18.48 FEET ALONG THE ARC OF A NON-THATCHED CURVE TO THE POINT MARKED A

THENCE NORTH 81° 22' 44" WEST, 124.81 FEET TO A POINT FOR CORNER;

THENCE, 343.25 FEET ALONG THE ARC OF A TANGENT CURVE TO THE RIGHT, HAVING A RADIUS

TRONCE, SOUTH 39° 34' 34" EAST, 88.78 FEET TO THE POINT OF BEGINNING AND CONTAINING



IN _____
COUNTY, TEXAS

A population of 17,018 cases of HPA collected in

JULY 18, 2014
JOB NO. 1931-6001-310

CHRIS LINDHOAST, PRESIDENT

LJA Engineering, Inc.

BRILL 15

