

PLAT RECORDING SHEET

PLAT NAME: Tamarron, Section 6

PLAT NO: _____

ACREAGE: 34.721

LEAGUE: J. D. Vermillion Survey, The A.G. Sharpless Survey

ABSTRACT NUMBER: 339, 322

NUMBER OF BLOCKS: 4

NUMBER OF LOTS: 108

NUMBER OF RESERVES: 4

OWNERS: D. R. Horton-Texas, Ltd. a Texas Limited Partnership

(DEPUTY CLERK)



1. The first step in the process of identifying a problem is to recognize that a problem exists. This involves gathering information about the situation and identifying the specific issue that needs to be addressed.

