



Defining the future of Mobile Healthcare.™

Customer Quote

Order No.: Q2311-0001

Quote Date: 12/12/2020

Expiration Date: 3/12/2021

Salesperson: Paul Brown

pbrown@frazerbilt.com

Invoice To:

Mary Beth Jackson
Fort Bend County EMS
Fort Bend County Auditor
301 Jackson Street
Richmond TX 77469

Attention:

Deputy Chief
Brian Petrilla
brian.petrilla@fortbendcountytexas.gov

Order Instructions:

This Quote is for a Remount of a Wrecked Unit on to a Customer Supplied Chassis. Wreck repair to Module will be completed by Frazer Service Department.

No.	Item	Quantity	U/M		Unit Price		Net Amount
1	MODULE Configurable Module	1.000	EA	\$	63,066.00	\$	63,066.00
2	CHASSIS 2021 Ram 3500 Diesel CP	1.000	EA	\$	500.00	\$	500.00
3	DELIVERY Customer to Pickup FOB Frazer	0.000	M	\$	2.75	\$	0.00
4	HGAC-RMT HGAC Contract # AM10-20	1.000	EA	\$	600.00	\$	600.00



Defining the future of Mobile Healthcare.™

Customer Quote

Order No.: Q2311-0001

Quote Date: 12/12/2020

Expiration Date: 3/12/2021

Remit To:

Frazer, Ltd.
7219 Rampart Street
Houston TX 77081

Sale Amount: 64,166.00

Sales Tax: 0.00

Total Amount: 64,166.00

Payment Terms: Net 30

Special Instructions:

Email this quote along with your PO to sales@frazerbilt.com.
Graphics pricing includes two hours' design time in the base price.
More extensive graphics or multiple changes will be billed at \$100/hr.



Defining the future of Mobile Healthcare.™

For your convenience, all module pricing has been itemized below per quote Q2311-0001 for Fort Bend County EMS :

Base Module	\$	21,900.00
Chassis Exterior	\$	13,625.00
Module Exterior	\$	24,441.00
Chassis Interior	\$	3,050.00
Module Interior	\$	50.00
Module Total	\$	63,066.00

Items included in above totals:

1. Old Chassis: Do nothing	\$	incl
2. Type I 12' Module	\$	incl
3. This is a CAAS Unit	\$	incl

Chassis Exterior:

4. Customer Provided Chassis processing fee	\$	500.00
5. Heat Shielding for Diesel Chassis	\$	1,575.00
6. Chassis : 2021 RAM 3500, Diesel, 4x2, Regular, 84" Cab to Axle, Dodge White (PW7)	\$	incl
7. Suspension: LiquidSpring	\$	11,550.00
8. Wheel type: Stainless steel covers	\$	incl
9. Passenger's side Grille Light: Whelen M4 Red Light	\$	incl
10. Driver's side Grille Light: Whelen M4 Amber Light	\$	incl
11. Passenger's side Intersect Light: Whelen M4 Red Light	\$	incl
12. Driver's side Intersect Light: Whelen M4 Red Light	\$	incl
Chassis Exterior Subtotal	\$	13,625.00

Module Exterior:

13. Onan 450 Hour Basic Preventative Maintenance	\$	incl
14. Stripe Chassis only	\$	incl
15. Hidden Switch Behind the Driver's Side Rear Bumper End Cap	\$	225.00
16. Reconnect Ignition Kill Switch	\$	125.00
17. UNOC- ???- Service Department repair of Module Wreck.	\$	15,341.00
18. UNOC-???- Furnish and instal meps genrstor and bracket under the hood. Module keep existing ACU. Reconnect to ACU in MOD.	\$	7,900.00
19. Lower BTTs: 2 Grote Lights on each side	\$	incl



Defining the future of Mobile Healthcare.™

20. Reconnect Door Locks on Entry Doors and Front I/O	\$	850.00
Module Exterior Subtotal	\$	24,441.00

Chassis Interior:

21. Siren Speakers: 2 CAST Speakers	\$	600.00
22. Tap-2 on Primary Siren	\$	incl
23. Siren Option: Whelen C9 Siren in Console	\$	incl
24. Mic 1 on passenger's side slot 1	\$	incl
25. Slot 1: Extended MDT plate - no swivel, no fuel gauge	\$	75.00
26. Slot 2: Single Slot Switch Panel	\$	incl
27. Slot 3: Radio Plate: 7.06 L X 2 W opening dims	\$	incl
28. Slot 4: Siren 1	\$	incl
29. Console Switch Layout : Primary - Secondary - Blank - Blank - Side Scene (Driver's Side) - Side Scene (Passenger's Side) - Rear Load - Interior Lights - Start/Stop Genset -	\$	incl
30. New Armrest	\$	225.00
31. Console Layout: 4-Slot Console	\$	incl
32. Floor in Front of Console: Gamber Johnson Heavy Dual Cup Holder	\$	175.00
33. Rear of Console: Single Mapholder	\$	225.00
34. Camera System: Voyager 7" Monitor with Back-Up Camera	\$	1,700.00
35. White Back-up Camera	\$	incl
36. UNOC-???- Furnish and install single on/off switch on center console position 3 to activate siren.	\$	50.00
37. UNOC-???- Furnish and install swith on center console position 4 to activate front scene light.	\$	incl
Chassis Interior Subtotal	\$	3,050.00

Module Interior:

38. Safety Yellow Powdercoated Grab Rails	\$	175.00
39. UNOC -??- keep existing grab bars. Credit	\$	-175.00
40. Action Wall Switch Layout : Existing Switch (interior lights); Existing Switch (dimmer); Existing Switch (ventialtion); Existing Switch (unlock/lock);	\$	incl
41. Rear Door Switch Layout : Acknowledge; Existing Switch (blank); Dump/Bypass (Suspension); Existing Rear Load;	\$	incl
42. Two Seating Positions at the Squad Bench - 2 and 3	\$	incl



Defining the future of Mobile Healthcare.™

43. Replace Overhead Grab Rail(s)	\$	incl
44. UNOC-???- Reconnect existing patien camera in module to Monitor	\$	50.00
Module Interior Subtotal	\$	50.00

All Frazer Remounts come standard with the following features:

Replacement of applicable chassis components such as:

- Push Bar, Grill Lights, Siren, Speakers, & aluminum powder-coated console
- Backup alarm, generator fuel tank, and mud flaps

450 hour Preventative Maintenance on an Onan generator (if applicable)

Shear-plate method of attachment securing the module to the chassis

New LED Flex Strips to replace all existing compartment lights

Full electrical check

New weather-stripping, ribbed rubber & compartment bumpers

Complete detail of module